

DPD 2890-59
4 May 1959

MEMORANDUM FOR: Chief, Materiel Branch, DPD-DD/P

SUBJECT : Elint Equipment Malfunction Report for April 1959

25X1A2d1

25X1A2d1 Detachment C - Mission CT-59-34. 2 April test flight for [REDACTED] 26 BA.
The power supply fuse blew in [REDACTED] 26 BA. It is believed that the fuse used is underrated. The fuse was replaced with a slow-blow fuse of same value. No further trouble was experienced.

25X1A2d1

Mission CT-59-38. 22 April test flight [REDACTED] 26 BA. HRE P band amplifier failed. The cause of the failure was poor soldering on the connection opening. The part was re-soldered, causing no further difficulty.

Detachment B - No malfunction report was received for April 1959. A request for the report has been made.

Detachment D - There were no failures in Detachment D during April 1959.

SIGNED

25X1A9a

[REDACTED]
Chief, Communications Section
DPD-DD/P

Distribution:

Orig & 1 - Addressee

- 1 - O-15
- ✓ 1 - RI
- 1 - Chrono

AWR/bs